

## Quotation Notes:

### Why Choose Tomlinson-Cannon?

#### DECADES OF LOYAL SERVICE

Serving our Customers Since 1948  
Dedicated & Highly Skilled Employees  
Best Products & Installation Methods  
LIFETIME GUARANTEES  
Most Jobs Completed In One Day  
We Install Year-Round, Including Winter  
Bank Financing Available  
Discover, Mastercard & Visa Accepted

CALL US TODAY!

### Other Services

#### Seamless Gutter Installation

Custom-fitted to your home by our experienced personnel with our mobile factory.

#### Basement Waterproofing

Our drain tile system or crack injections are guaranteed to dry up your wet basement.

#### Basement Wall Anchoring

If your basement walls are cracked or bowed, our "Grip-Tite" anchor system is guaranteed to solve the problem quickly and simply without excavation or disturbing outside concrete and landscapes.

Not responsible for stress cracks occurring during lifting process.



# Tomlinson Cannon

## MUDJACKING

### Re-level & Restore:

Driveways, Patios, Sidewalks,  
Porches & Any Concrete Slab



Call Us Today for a  
Prompt, Free Quote!

Iowa City (Main): 319-774-3422

Cedar Rapids: 319-774-3422

Davenport: 563-362-3237

Waterloo: 319-409-6850

[tomlinson-cannon.com](http://tomlinson-cannon.com)

## What you can expect if you don't restore your sunken concrete.

- Basement water leaks.
- Cracked and bowing foundation walls.
- Erosion of landscaping.
- Unsightly cracking of concrete.
- Depreciated value of home.
- Liability hazards from tripping.

## Why does concrete sink?

Settling of sub-soil caused by erosion (washing out) or poorly compacted fill.



## Why Mudjacking?

- 1/2 the Cost
- Clean
- Saves Landscaping
- Complete in Less Than One Day
- Light Equipment
- Ecologically Sound

# MUDJACKING EXPLAINED STEP BY STEP

1.

A series of 2½" holes are strategically drilled on the settled side of the slab for raising and support.



2.

Using our custom-made "McCabe Mudjacker" we pump under pressure, into the holes, in alternating sequence, a mixture of agricultural products (Lime and Portland). The voids are filled and the slab is raised and restored to its original condition.

3.

Re-Cement Holes

4.

Clean-up